

LORD Comporation 2000 West Grandview Blvd. Erie, PA 16509-1029 USA +1 814 868 0924 www.lord.com

Mr. David P. Turner, RPM (3HS22) Western PA Section United States Environmental Protection Agency, Region 3 1650 Arch Street Philadelphia, PA 19103-2029

January 24, 2011

Reference:

LORD-Shope RA Monthly Progress Report

Dear Mr. Turner:

LORD is hereby submitting two copies of the monthly progress report for the period of December 1, 2010 through December 31, 2010.

The following work was conducted during this period:

## REMEDIAL ACTION

NPDES Report:

The December report will be submitted under a separate cover.

Thermal Oxidizer:

The thermal oxidizer was shutdown for the year on November 4, 2010.

Groundwater Treatment:

The groundwater treatment system was operating normally during this interim.

The groundwater TOC effluent concentration was 1.5 mg/l.

Sincerely,

LORD Comporate

George M. Kickel

Director, Environment, Safety, Health, and Regulatory Compliance they also engine to the grant of their

- ARCADIS, Inc.

gaz verge gerike versioner av av av et er er et efter

John Morettini, PADEP